

ABRASIVE WHEEL CUT-OFF

1. Only properly trained and authorized employees are permitted to do abrasive cut-off.
2. Read and follow manufacturers recommendations.
3. Always wear protective eye glasses or face shield.
4. Keep working area clean.
5. Never use cut-off tools around flammable liquids or gases.
6. Do not wear loose clothing or jewelry with cut-off tools.
7. Always secure work place.
8. Do not over reach, keep footing and balance at all times.
9. Always unplug tool before servicing or when not in use.
10. Inspect before use: for damaged parts, cut-off discs, and cords for cracks or damage, all guards and shields in place.
11. Always cut so sparks do not contact you or someone else.
12. Always work with proper lighting.

Date