

HOT TAR BUCKET

1. Employees will be properly and thoroughly trained before attempting to do any work with or on any Hot Tar Bucket.
2. Read and understand the Operations Manual.
3. Wear gloves with wristlets. Do not wear gauntlet style gloves.
4. Wear long sleeve shirt with sleeves rolled down and cuffs buttoned.
5. Wear facemask when loading or charging bucket with material and cleaning.
6. Load bucket from ground level.
7. Keep material door closed at all time except when adding material.
8. Never stand on any part of the machine.
9. Do not pull, twist, stretch or kink the material hose.
10. Do not operate without safety cover on hose.
11. Wear heavy leather boots or shoes.
12. Wear long pants with no cuffs.
13. Never allow another person to adjust or operate the controls while you are sealing or cleaning the unit.
14. Do not overfill the melting tank. For best results, add only as much material as required for the job or a maximum of 75% of tank capacity.

Date